

### 測試報告

**Test Report** 

號碼(No.): ETR25103539 日期(Date): 17-Jan-2025 頁數(Page): 1 of 4

南亞塑膠工業股份有限公司嘉義二廠 (NAN YA PLASTICS CORPORATION (CHIA-YI 2ND PLANT)) 嘉義縣太保市南新里北港路二段201號 (201, SECTION 2, PEI-KANG RD, TAI-BAO, CHIA-YI, TAIWAN)

以下測試樣品係由申請廠商所提供及確認 (The following sample(s) was/were submitted and identified by the applicant

as):

送樣廠商(Sample Submitted By) : 南亞塑膠工業股份有限公司嘉義二廠 (NAN YA PLASTICS CORPORATION (CHIA-YI

2ND PLANT))

樣品名稱(Sample Name) : BIAXIALLY ORIENIED POLYPROPYLENE FILM (雙軸延伸聚丙烯膜)

收件日(Sample Receiving Date) : 10-Jan-2025

測試期間(Testing Period) : 10-Jan-2025 to 17-Jan-2025

測試需求(Test Requested) : 依據客戶指定,測試鹵素-氟、氯、溴、碘。 (As specified by client, to test

Halogen-Fluorine, Chlorine, Bromine, Iodine in the submitted sample.)

測試結果(Test Results) : 請參閱下一頁 (Please refer to following pages).

Troy Chang / Department Malager Signed for and on behalf of Arwan SGS TAIWAN LTD. Chemical Laboratory - Taipei





## 測試報告

## **Test Report**

號碼(No.): ETR25103539 日期(Date): 17-Jan-2025 頁數(Page): 2 of 4

南亞塑膠工業股份有限公司嘉義二廠 (NAN YA PLASTICS CORPORATION (CHIA-YI 2ND PLANT)) 嘉義縣太保市南新里北港路二段201號 (201, SECTION 2, PEI-KANG RD, TAI-BAO, CHIA-YI, TAIWAN)

#### 測試部位敘述 (Test Part Description)

No.1 : 透明塑膠膜 (TRANSPARENT PLASTIC FILM)

#### 測試結果 (Test Results)

測試項目	測試方法	單位	MDL	結果
(Test Items)	(Method)	(Unit)		(Result)
				No.1
氟 (F) (Fluorine (F)) (CAS No.: 14762-	參考BS EN 14582: 2016,以離子層析儀分析。	mg/kg	50	n.d.
94-8)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			
氯 (Cl) (Chlorine (Cl)) (CAS No.:	參考BS EN 14582: 2016 · 以離子層析儀分析。	mg/kg	50	n.d.
22537-15-1)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			
溴 (Br) (Bromine (Br)) (CAS No.:	參考BS EN 14582: 2016·以離子層析儀分析。	mg/kg	50	n.d.
10097-32-2)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			
碘 (I) (Iodine (I)) (CAS No.: 14362-44-	參考BS EN 14582: 2016·以離子層析儀分析。	mg/kg	50	n.d.
8)	(With reference to BS EN 14582: 2016, analysis			
	was performed by IC.)			

#### 備註(Note):

- 1. mg/kg = ppm; 0.1wt% = 0.1% = 1000ppm
- 2. MDL = Method Detection Limit (方法偵測極限值)
- 3. n.d. = Not Detected (未檢出); 小於MDL / Less than MDL




# 測試報告 Test Report

號碼(No.): ETR25103539 日期(Date): 17-Jan-2025 頁數(Page): 3 of 4

南亞塑膠工業股份有限公司嘉義二廠 (NAN YA PLASTICS CORPORATION (CHIA-YI 2ND PLANT)) 嘉義縣太保市南新里北港路三段201號 (201, SECTION 2, PEI-KANG RD, TAI-BAO, CHIA-YI, TAIWAN)

#### 鹵素分析流程圖 / Analytical flow chart - Halogen





# 測試報告 Test Report

號碼(No.): ETR25103539

日期(Date): 17-Jan-2025

頁數(Page): 4 of 4

南亞塑膠工業股份有限公司嘉義二廠 (NAN YA PLASTICS CORPORATION (CHIA-YI 2ND PLANT)) 嘉義縣太保市南新里北港路三段201號 (201, SECTION 2, PEI-KANG RD, TAI-BAO, CHIA-YI, TAIWAN)

\* 照片中如有箭頭標示,則表示為實際檢測之樣品/部位. \* (The tested sample / part is marked by an arrow if it's shown on the photo.)

### ETR25103539



\*\* 報告結尾 (End of Report) \*\*